

- Key
- Site Boundary
 - Site Boundary 250m
 - Buffer


Scale 1:10,000 @ A3

0 0.25 0.5 Km



Figure 6.4
Peat Condition Assessment Survey
Results Pg 1 of 6

Achany Extension Wind Farm
Section 36C: EIA Report



Contains OS data © Crown Copyright and database right 2025
Contains data from OS Zoomstack, Sources: Esri, Maxar, Airbus DS, USGS, NGA, NASA, CGIAR, N Robinson, NCEAS, NLS, OS, NMA, Geodatastyrelsen, Rijkswaterstaat, GSA, Geoland, FEMA, Intermap, and the GIS user community

- Key**
- Site Boundary
 - Site Boundary 250m Buffer
 - Access Track

- Peatland Condition Categories**
- Modified
 - Modified/Drainage
 - Modified/Drainage/Actively Eroding
 - Near Natural


Scale 1:10,000 @ A3

0 0.25 0.5 Km



Figure 6.4
Peat Condition Assessment Survey
Results Pg 2 of 6

Achany Extension Wind Farm
Section 36C: EIA Report



Key


- Site Boundary
- Site Boundary 250m
- Buffer

Access Track

Hardstands

Peatland Condition Categories

- Modified
- Modified/Drainage
- Modified/Drainage/
Actively Eroding
- Near Natural



Scale 1:10,000 @ A3

0 0.25 0.5 Km

N

Figure 6.4
Peat Condition Assessment Survey
Results Pg 3 of 6

Achany Extension Wind Farm
Section 36C: EIA Report

Esri, Intermap, NASA, NGA, USGS, Contains OS data © Crown Copyright and database right 2025
Contains data from OS Zoomstack


Key

- Site Boundary
- Site Boundary 250m
- Buffer

- Access Track
- Hardstands

Peatland Condition Categories

- Modified
- Modified/Drainage
- Modified/Drainage/
Actively Eroding



Scale 1:10,000 @ A3

0 0.25 0.5 Km

N

Figure 6.4
Peat Condition Assessment Survey
Results Pg 4 of 6

Achany Extension Wind Farm
Section 36C: EIA Report

Key

- Site Boundary
- Site Boundary 250m Buffer
- Access Track
- Hardstands

Peatland Condition Categories

- Modified
- Modified (Near Natural)
- Modified/Drainage/Actively Eroding
- Near Natural


Scale 1:10,000 @ A3

0 0.25 0.5 Km



Figure 6.4
Peat Condition Assessment Survey
Results Pg 5 of 6

Achany Extension Wind Farm
Section 36C: EIA Report



Key

- Site Boundary
- Site Boundary 250m Buffer
- Access Track
- Hardstands

Peatland Condition Categories

- Modified
- Modified (Near Natural)
- Modified/Drainage/Actively Eroding
- Near Natural





Figure 6.4
Peat Condition Assessment Survey
Results Pg 6 of 6

Achany Extension Wind Farm
Section 36C: EIA Report